

## **Correction to Recommended Practice vol. 11.**

### **Wind Speed Measurement and use of cup anemometry**

The last sentence in paragraph 5.1 on page 16 is

".....roughly 8.5 boom diameters."

Shall be

".....roughly 8.5 mast diameters."